

Austin Highway intersection with Salado Creek San Antonio, Texas



Early 20th Century



August 24, 2013

color photos by Stephen Colley
sepia photo photographer unknown



Reinforcing steel now exposed on the surface of the bridge indicates the early reinforcing bars were twisted steel bars, possibly similar to steel ribbons.